



380 Kettleby Road,
Kettleby, Ontario L0G 1J0
Tel: 905-751-0823
Fax: 905-727-4001

www.kingnorth.com

NON-DESTRUCTIVE TESTING

August 14, 2001

Our Project: UST 8888-888

Mr. John Jones, Property Manager
TopCorp Management Services Limited
300 1st Road
Yourcity, Ontario
X1A 2M3

**Subject: Structural Condition Analysis Report of Parking Lot Light Standards at The Best Plaza,
1550-1556 Big Top Road, Mytown, Ontario, June 14, 2001**

Dear Mr. Jones:

As per your request, The King North Group has completed a condition assessment of eight (8) light standards at the above noted facility.

This report has been prepared for TopCorp Management Services Limited and third party use of this report without the consent of The King North Group is prohibited.

The enclosed report outlines in detail, the condition of and repairs required on the steel posts for the light standards and concrete support bases.

We trust that this information is clear, however if you should have any questions on the contents of this report, please do not hesitate to call.

Yours truly,
The King North Group (1118219 Ontario Limited)

A handwritten signature in black ink, appearing to read "Edward Litow". The signature is stylized with a large, looping "E" and a cursive "Litow".

Edward Litow, B. Tech. (Arch Sc.)



380 Kettleby Road,
Kettleby, Ontario L0G 1J0
Tel: 905-751-0823
Fax: 905-727-4001

www.kingnorth.com

STRUCTURAL CONDITION ANALYSIS REPORT
OF
PARKING LOT LIGHT STANDARDS
AT
THE BEST PLAZA
MYTOWN, ONTARIO
PREPARED FOR
TOPCORP MANAGEMENT SERVICES LIMITED

Prepared By:
THE KING NORTH GROUP
380 Kettleby Road
Kettleby, Ontario
L0G 1J0

Project No. UST 8888-888

JUNE 2001

TABLE OF CONTENTS

1.0	EXECUTIVE SUMMARY SPREADSHEET	1
2.0	OBSERVATIONS	4
3.0	CONCLUSIONS AND RECOMMENDATIONS	9

SCHEMATIC DRAWING OF POLE LOCATIONS

1.0 EXECUTIVE SUMMARY SPREADSHEET

At the request of Mr John Jones, Property Manager for TopCorp Management Services Limited, The King North Group, performed a condition assessment/inspection of eight (8) parking lot light standards at The Best Plaza in Mytown, Ontario. Our report reflects the conditions in effect June 14, 2001 during our ultrasonic inspections and visual observations.

Concrete Bases:

Our findings revealed that all the concrete bases for the eight (8) poles covered in the scope of work are in good condition. There are currently no areas of concern respecting these structural elements of the light standard.

Light Standards:

According to the identification labels on the poles, the oldest poles are eight years old (1993). The newest poles are 3 years old (1988). Seven of the eight poles require maintenance to address exterior corrosion. The corrosion is currently limited to exterior surface conditions and to a minor degree the interior surfaces. The degree of corrosion is still limited to surface and has not significantly affected the wall thickness of the tube poles. All inspected poles have wall thickness within the stated specifications of the standard for the industry.

With diligent maintenance procedures i.e. recoat (with corrosion protective paint) all exterior surfaces, the poles should continue to perform trouble free in terms of their structural integrity.

Following is a Summary Spreadsheet of our findings and maintenance recommendations:

POLE I.D. #	CONDITION OF POLE (Shape, height, colour, # fixtures)	MAINTENANCE REQ'D (BY PRIORITY)			YEAR MAINTENANCE REQUIRED		
		P1	P2	P3	2001	2002	2003
1.	STEEL POLE: GOOD POWCO: 9"X9" tube, tapered, 40 ft., painted white. Surface corrosion S. side of pole base to half height of pole. Minor corrosion interior. CONCRETE BASE: GOOD Unpainted	N/A	1. Remove surface corrosion, prime and repaint.		Yes	N/A	N/A
2.	STEEL POLE: GOOD POWCO: 9"X9" tube, tapered, 40 ft., painted white. Minor surface corrosion S. side. CONCRETE BASE: GOOD Unpainted	N/A	1. Remove surface corrosion, prime and repaint.	N/A	Yes	N/A	N/A
3.	STEEL POLE: FAIR DYNAPOLE: 8" x8" square tube, tapered, 40ft, painted white. Significant corrosion on S. side of pole. CONCRETE BASE: GOOD Unpainted.	1. Remove surface corrosion and repaint.	N/A	N/A	Yes	N/A	N/A
4.	STEEL POLE: FAIR DYNAPOLE: 8" x8" square tube, tapered, 40ft, painted white. Minor surface corrosion W. side exterior at base. Minor corrosion interior CONCRETE BASE: GOOD Unpainted.	N/A	1. Remove surface corrosion, prime and repaint.	N/A	Yes	N/A	N/A
5.	STEEL POLE: GOOD DYNAPOLE: 8" x8" square tube, tapered, 40ft, painted white. Surface corrosion at base of pole. Minimal interior corrosion. CONCRETE BASE: GOOD Unpainted.	N/A	1. Remove surface corrosion, prime and repaint.	N/A	Yes	N/A	N/A

E BEST PLAZA, MYTOWN

POLE I.D. #	CONDITION OF POLE (Shape, height, colour, # fixtures)	MAINTENANCE REQ'D (BY PRIORITY)			YEAR MAINTENANCE REQUIRED		
		P1	P2	P3	2000	2001	2002
6.	STEEL POLE: GOOD DYNAPOLE: 8" x8" square tube, tapered, 40ft, painted white. Surface corrosion at base of pole. Minimal interior corrosion. CONCRETE BASE: GOOD Unpainted.	N/A	1. Remove surface corrosion, prime and repaint.	N/A	Yes	N/A	N/A
7.	STEEL POLE: FAIR SPINA STEEL WORKERS: 9"X9" tube, tapered, 40ft., white. No surface corrosion. No interior corrosion. CONCRETE BASE: GOOD Unpainted.	N/A	N/A	N/A	N/A	N/A	N/A
8.	STEEL POLE: GOOD STEEL POLE: GOOD DYNAPOLE: 8" x8" square tube, tapered, 40ft, painted white. Minor surface corrosion at base of pole and S. surface. Minor surface corrosion S. side of pole. Minimal interior corrosion. CONCRETE BASE: GOOD Unpainted.	N/A	1. Remove surface corrosion, prime and repaint.	N/A	Yes	N/A	N/A

2.0 OBSERVATIONS

Following is our detailed information of our field observations of the steel light pole standards at the building.

Our Scope of Work was based on the following:

1. Visual Inspection:

Components inspected included:

- | Light Standard/Pole | Concrete Base |
|----------------------|----------------------|
| ▪ Threaded rod | ▪ Exterior finish |
| ▪ Levelling nuts | ▪ Plumb in elevation |
| ▪ Washers | |
| ▪ Hex nuts | |
| ▪ Nut covers | |
| ▪ Base plates | |
| ▪ Handholes | |
| ▪ Tube | |
| ▪ Plumb in elevation | |

2. Test Reading

- | Light Standard/Pole | Concrete Base |
|---------------------------------|------------------|
| ▪ Ultrasonic thickness readings | ▪ Hammer testing |

The steel thickness readings were captured with a Gilardoni DG41 EZ Portable Ultrasonic non-destructive Digital Indicating Thickness Testing Gauge. This is an ultrasonic testing device that utilizes a double transducer probe emitting a 4 MHz ultrasonic pulse into the steel to be measured. The probe is especially designed to gauge thickness of rough or corroded metals.

Based on our observations, the conditions were assigned a condition and maintenance priority rating indicative of the degree of severity of the conditions

Our condition ratings are described as follows:

GOOD CONDITION

Components of light pole (**concrete base (if applicable), metal base plates, anchor bolts, cover plates, pole tube**) are not physically damaged and are not an immediate structural concern.
Probability of failure of the pole i.e. collapse is minimal to none.

FAIR CONDITION

Components are physically damaged i.e. corroded, cracked and/or broken, loose, misshapen, however are not an immediate structural concern.
Possibility of failure of the pole i.e. collapse, is low.

POOR CONDITION

Components are physically damaged i.e. corroded, cracked and/or broken, loose, misshapen, resulting in structural integrity concerns.
Possibility of failure of the pole i.e. collapse, is high.

Our Priority ratings are determined as follows:

Priority 1: HIGH MAINTENANCE PRIORITY:

Immediate maintenance attention is required.

Priority 2: MEDIUM MAINTENANCE PRIORITY:





Maintenance attention required as soon as possible.





Priority 3: LOW MAINTENANCE PRIORITY:

Components require only routine maintenance attention.

SUMMARY CHART OF OBSERVATIONS

The following chart summarizes our field observations.

LIGHT POLE #	METAL TESTING RESULTS							
	THICKNESS (In.)				REMARKS			
	Min. Spec'd: .125/35' pole .149/40' pole							
	N	S	E	W	Condi tion	Prio rity	Comments	Sample Photographs
1 9"x9" Square tube tapered 40 ft., 2 head	.131 .126 .127 .131 .139	.203 .135 .138 .134 .178	.131 .131 .133 .134 .147	.138 .135 .133 .132 .140	Good	2	1. Surface corrosion S. side of pole base to half height of pole. Minor corrosion interior.	
2 9"x9" Square tube tapered 40 ft., 2 head	.143 .134 .138 .129 .125	.144 .128 .125 .125 .135	.135 .138 .137 .135 .136	.130 .132 .133 .136 .144	Good	2	1. Minor surface corrosion S. side. No corrosion interior.	
3 8"x8" Square tube tapered 40 ft., 2 head	.094 .073 .078 .100 .201	.120 .121 .105 .197 .197	.095 .210 .115 .118 .074	.071 .070 .074 .081 .081	Fair	1	1. Significant corrosion on S. side of pole.	
4 8"x8" Square tube tapered 40 ft., 2 head	.205 .121 .208 .210 .079	.077 .090 .081 .080 .080	.092 .070 .075 .094 .101	.117 .074 .205 .208 .259	Good	2	1. Minor surface corrosion W. side exterior at base. Minor corrosion interior	

LIGHT POLE #	METAL TESTING RESULTS							
	THICKNESS (In.)				REMARKS			
	Min. Spec'd: .125/35' pole .149/40' pole							
	N	S	E	W	Cond ition	Prio rity	Comments	Sample Photographs
5	.233	.091	.239	.139	Good	2	1. Surface corrosion at base of pole. Minimal interior corrosion.	
8"x8"	.237	.078	.086	.225				
Square	.223	.120	.074	.218				
tube	.235	.094	.074	.212				
tapered	.203		.205	.218				
40 ft.,								
2 head								
6	.232	.238	.242	.230	Good	2	1. Surface corrosion at base of pole. Minimal interior corrosion.	
8"x8"	.230	.248	.240	.233				
Square	.230	.249	.238	.119				
tube	.217	.223	.234	.096				
tapered	.217	.111	.252	.234				
40 ft.,								
2 head								
7	.219	.200	.217	.270	Good	2	1. No surface corrosion. No interior corrosion.	
9"x9"	.219	.200	.217	.223				
Square	.203	.205	.207	.203				
tapered	.200	.205	.203	.200				
2 head	.203	.207	.202	.201				
8	.229	.211	.211	.216	Good	2	1. Minor surface corrosion at base of pole and S. surface. 2. Minor surface corrosion S. side of pole. 3. Minimal interior corrosion. 4. No bolt covers.	
8"x8"	.240	.208	.214	.222				
Square	.242	.208	.216	.223				
tube	.235	.209	.214	.220				
tapered	.231	.226	.216	.229				
40 ft.,								
2 head								



IRES 8888 888
THE BEST PLAZA
TOPCORP MANAGEMENT SERVICES LIMITED

- NOTE:
1. Our minimum required thickness values for the metal thickness were based on manufacturer's information (Powco in Barrie, Ontario). The poles installed at this site have been designed for a maximum EPA of 7ft² @ 70mph (including a 1.3 gust factor) with a minimum wall thickness estimated to be 9 gauge metal (0.1495 in.) for round and square poles as well as tapered square and octagonal poles up to 40 ft..
 2. Standard of the industry states that minimum wall thickness for round and square poles as well as tapered square and octagonal poles up to 40 ft in height is 11 gauge metal (0.1233 in.). This is for a pole loading maximum EPA of 10ft² @ 100mph (including a 1.3 gust factor).

Based on these results the structural condition of the poles with respect to wall thickness integrity is good.

CONCRETE BASES

The concrete bases for all light poles were tested by hammer test soundings and were found to be in good condition. They will not be considered further in this report.

3.0 CONCLUSIONS AND RECOMMENDATIONS

All existing light standards are in acceptable structural condition (based on the stated criteria) and require only routine maintenance at this time. Seven of the eight are exhibiting signs of surface corrosion and will require remedial maintenance work i.e. sandblasting and recoating, in specific locations.

While corrosion is present, it has not at this time affected the wall thickness of the light standards to any significant degree. They should however be monitored/tested on a regular basis (3 to 5 years minimum) to ensure the remedial work has addressed and halted further corrosion of the metal tubing which comprises the poles. They should also be visually inspected (by staff) for signs of premature corrosion after every winter season. This would allow for maintenance to be performed to prevent premature damage to the poles.




IRES 8888 888
THE BEST PLAZA
TOPCORP MANAGEMENT SERVICES LIMITED

SCHEMATIC DRAWING (NTS) OF POLE LOCATIONS

The Best Plaza
MYTOWN, ONTARIO

SCHEMATIC DRAWING OF POLE LOCATIONS



POLE LOCATIONS

THE BEST Plaza

1550-1556 Big Top Road

Mytown, Ontario

(NOT TO SCALE)